



## Anonymised Case Studies

### Case study 1 – Multi-site compliance testing

Programme of electrical inspection and testing across multiple operational buildings.

Clear defect categorisation, remediation planning and compliant certification.

### Case study 2 – Remedial works following EICR

Delivery of remedial works in occupied premises following inspection findings.

Phased delivery to minimise disruption and maintain safety.

### Case study 3 – Emergency lighting upgrades

Upgrade and verification of emergency lighting systems in public buildings.

Testing, commissioning and documented handover.